

VEHICULO	DOMINIO	MOTOR CUADRO
MOTO S/D	DK50X4686	DK50XF1504662
MOTO S/D	700727	*70727*
MOTO S/D	50A804637	TL06364
MOTO S/D	50L624947	ZH11622ASC259
MOTO S/D	50LC18312	TQ19434 AGV140
MOTO S/D	50VJ06030	TI04588
MOTO S/D	#19C0706#	H19-00706
MOTO S/D	EB002950	EB002950
MOTO S/D	543521	SV2-09320
MOTO S/D	A122-136526	CA19A-136501
MOTO S/D	DK50XF-1093265	DK50XF1187705
MOTO S/D	EB306440	M0394M1BR/RC311043
MOTO S/D	EB221660	CB222593
MOTO S/D	DK50XE-1112096	DK50XF1206715
MOTO S/D	TR28507 ALH168	TR28507/ALH168
MOTO S/D	OAE09530	TP21857/ADY193
MOTO S/D	96C18000371	96C180007577
MOTO S/D	97K18020071	97J18020163
MOTO S/D	024388	REARMADO (CACERO)
MOTO S/D	103164	G*13164*
MOTO	360AUY	4GF-002793 4GF-002793
MOTO S/D	D228304	D278523
MOTO S/D	50AE21686	TQ62963
MOTO S/D	50LE02013	TQ03456/AGA016
MOTO S/D	EB001096	1AQ004
MOTO S/D	4EN-001421	EN001421
MOTO S/D	L34840	34840
MOTO S/D	DK50XE1066054	DK50XFA-163435
S/D	44835	44835
MOTO S/D	6C006059	6D006045
MOTO S/D	DK50XE1079656	DK50XE1175594
MOTO S/D	0037058	053471
MOTO S/D	009076	10661
MOTO S/D	50LD35116	TP55262/AFN395
MOTO S/D	EM12-2115	8AHJ15050XK002670
MOTO S/D	HF01E-2307567	HF011305122
MOTO S/D	*31915*	31915
MOTO S/D	50LF21334	TNO3922/ABI872
MOTO S/D	DK50XE1078228	DK50XF1174356
MOTO S/D	50AD02151	T612114
MOTO S/D	DK50XE-1093290	DK50XF1187898
MOTO S/D	50LG11483	TR95083APY736
MOTO S/D	50LG118629	ILEGIBLE
MOTO S/D	50AF24948	T073472/AJH539
MOTO S/D	FM12-2115	BAHJ15050XR02301
MOTO S/D/441IVQ	DK50XF1096196	DK50XF1190815
CUATRICICLOS/D	JA100*001535	*001535
MOTO S/D	NUMERO GASTADO	NO TIENE (ES REARMADO)
MOTO S/D	C90E-200009JL70-2/*96012886*	
MOTO S/D	50LG19338	TP232244ADZ550
MOTO S/D	DK50XE111672	DK50XF1211583
MOTO S/D	50AE/08260	ADULTERADO (SOLDADO)

MOTO S/D 1P52FMH\*55091662\* \*LRYXCHLA466900709\*  
MOTO S/D AF05E-311164 3H1AF1603ND300311  
MOTO S/D 50AE10274 ILEGIBLE (LIMADO)  
MOTO S/D C1P50FMG-\*99070103\* LWGPCGL3XX1001553  
MOTO S/D 4001518 8ELM0515048001518  
MOTO S/D 50AF21733 TQ61942/AIW144  
MOTO S/D FA50-555498 FAS0448106FA50-555498  
MOTO S/D 1P52FMH\*06AD4274\* E54XCH3461004304  
MOTO S/D 316622 ALJET-Q939DOCPA/BO1024  
MOTO S/D \*08073\*  
MOTO S/D B1483Z1254 B9534  
MOTO 452CNA JL1P50FMH/\*04A952131\* LYLXCGL5951009522  
MOTO S/D K157FM\*97013824\* QM125-2B\*97005339  
MOTO S/D 280319921 OOO6076  
MOTO S/D 50LF01634 OOO5242  
MOTO S/D 50AD08898 TN21124ACD458  
MOTO S/D L26442 26442  
MOTO S/D \*597316\* 97316  
MOTO S/D 147FM-2B/\*940607043\* \*9406554\*  
MOTO 860CXR IP50FMH\*05111811\* LYLXCGL5561000446  
MOTO S/D DK50XE1093661 DK50XF1188123  
MOTO S/D 8AJ15350XR001295  
MOTO 036CFD HA07E-X106247 9C2HA070XR16247  
MOTO S/D \*33530\* \*33530\*  
MOTO S/D 50LG28545 8AGM550AA65043786  
MOTO S/D 50LF02607 ZH04101ARN747  
MOTO S/D 1P52FMH0790091 LSRXCHLC971200644  
MOTO S/D IV-010138 O10738  
MOTO S/D IP52FMH/\*06AD3182\* LJ4XCHLJ861003478  
MOTO S/D NH0707 9C8M19D2XKM000556  
MOTO S/D 50L626699 TN29095AC0435  
MOTO S/D DK50XE1089204 DK50FX1183907  
MOTO S/D 1PFMH\*60557702 LPYCHLOX6102109  
MOTO S/D KB20\*3910340\* XLC2P8001083901167X  
MOTO S/D EI03424318 BE11A-182810  
MOTO S/D LF1P50FMH\*71040600\* LYLXCGL5X71061793  
MOTO S/D C52\*96042156\* QM100\*9650126\*  
MOTO S/D 147FMD\*0601291 \*9PAABBBBC16A000331\*  
MOTO S/D JC152FMHRD81001921 \*LJCXCHLG981000701\*  
MOTO S/D JL1P39FMB2001001265 \*LAAXCBLAO/10002754\*  
MOTO S/D DJ152FMH\*070130717\* LCLXBHLG979000321  
MOTO S/D 50AH19855 ILEGIBLE  
MOTO S/D JC25ER2516464 9C2JC2501RR51648  
MOTO S/D 4EN-00305 4EN-00305  
MOTO S/D DK50X-106095 DK50XF1157970  
MOTO S/D \*24-01056\* #D-7757#  
MOTO S/D QJ150FMH\*80009296\* NO SE UBICA  
MOTO S/D LC152FMHX03897-96 \*LLCXCHLL571B71529  
MOTO S/D BB04287 CB00864AKJ599  
MOTO S/D 30-602573 REARMADO S/N  
MOTO S/D 50VKO5645 TKO7462  
MOTO S/D 1P50FMG-2\*10201869\* LWGPCGL3711000383  
MOTO S/D ZS156FMI-02073412 LZSPCLE4Y1002986  
MOTO S/D EA8351 CA84433

MOTO 543CJP 147FM-4\*97015798 JD90\*97011767\*  
MOTO S/D LF1P50FMH71028405\* LWJKCHL4472014274  
MOTO 737BCN 307975 307975  
MOTO S/D DK50XE1110908 DK50XE1250464  
MOTO S/D SK150FMG\*0500001517 9PDABBBDD151107819  
MOTO S/D F103218956 5F11B104341  
MOTO S/D IP52FNH08050895 LRYXXHLA380910461  
MOTO S/D Z5150FMH\*16311402\* NO SE ENCUENTRA  
MOTO S/D IP52FMH\*08AD3197\* LJ4XCHLJ781011204  
MOTO S/D DK50XE1159461 DK50XF1511109  
MOTO S/D 1P52FMH\*66090661\* LRYXCHLB266900261\*  
MOTO S/D 1P52FMH/\*06AD3768\* J4XCHLF461000833  
MOTO S/D ZS150FMG-A\*0208263\* LZSXGLH3Y1002782  
MOTO S/D 50LE09359 REARMADO  
MOTO S/D HA07E-4012539 9C2HA07004R012539  
MOTO S/D 50AB00320 TL07787  
MOTO S/D SDH150FMG2\*65147987\* \*LTMPCGB2365151041\*  
MOTO S/D QJ153FMH-2/\*67058663\* LAWXEHOA06B35298  
MOTO S/D JC152FMHRD81000889 LJXCXCHLG481000492  
MOTO S/D 50LG22082 REARMADO  
MOTO S/D 152FMH\*60552595\* DK50XF1508582  
MOTO S/D DK50XE311059619 DK50XF1220843  
MOTO 689CXR 1P52FMH71006337 \*LF3XCGB0X73000745\*  
MOTO S/D JC26E-SSA5223 9C2JC25015RSA5223  
MOTO S/D JC152FMH/\*RD81001044\* \*LJXCXCHLG981000584\*  
MOTO S/D QJ153FMH-2/\*0518714\* LAWXEHOAGYAO09958  
MOTO S/D KHIAH110AEA32765 AH110A-A32765  
MOTO S/D LG152FMHZ85000790 LCLXBHL689100790  
MOTO 159EKP 2F1P50FMH\*81021770\* LYLXCGL1181004266  
MOTO S/D M152FMH/\*Z060000345\* 8A6MBSCAC6C001401\*  
MOTO S/D LF1P50FMH\*71033947\* LWGXCH24772014771  
MOTO S/D E338B-045910 20039C6KE044040048430  
MOTO S/D E337E-104311 9C6KE042050044047  
MOTO DXR630 JC156FMI\*TM81005001\* LJCFCJVX81000904\*  
MOTO S/D D1P52FMH\*08200848 SRXCHLC48120130  
MOTO S/D 152FMHC5611171\* \*9PCACDE415L200909\*  
MOTO S/D RGOE510111246 9C2JC30501TRO11246  
MOTO 709ECJ LC1P50FMH\*08052792\* LYLXTGL5981121242  
MOTO S/D 152FMH22389LB7PCHLB282107119  
MOTO S/D 1P52FMH\*08060754\* LRYXCHLA980009193  
MOTO S/D QJ157FMI\*033657 LAWPEJOU3YA437124  
MOTO 233EHX 1P50FMH\*06136690\* LYLXCCL5761035585  
MOTO S/D 1P52FMH\*06AD3695\* LJ4CHLF36100070  
MOTO 868DXR 152FMH\*61175275\* \*LP7XCHL0860102807\*  
MOTO 986AYA 50AE007079 TP18854ADV030  
MOTO LIMADO LIMADO  
MOTO S/D IP52FMH\*08013591\* 8A6MBSCAC8C90647  
MOTO S/D 1P52FMH61173269 LP7XCHL0760102861  
MOTO CAT282 CB\*92515\* \*92515\*  
MOTO S/D 162FMJ\*81001915\* \*LF3YCK3A280000470\*  
MOTO S/D SDH150FMG2\*65084881\* \*LTMPCGB2965089564\*  
MOTO S/D KA110EE188902 MH4KA1100XKPC8146  
MOTO S/D LF1P50FMHA1060179\* LYLXCGL55A1148072  
MOTO DAR729 152FMH\*06126653\* LB7PCHLE062062219

MOTO S/D 163FML\*HA0112267\* 8AGYCM200Z9C200376  
MOTO 574DAR JLTP50FMH/\*05A115007\* LYLXCGL135101282  
MOTO S/D 152FMH\*61173213\* S/N  
MOTO HEV494 JC265E5580121 9C2JC2501SRS80121  
MOTO S/D Q157FMH021630 LAWPEJ002YA3  
MOTO S/D E104-1D567121 MHDRC100PWJ345693  
MOTO S/D 8112523 9C2JC30708R512523  
MOTO S/D JL25E5585476 9C2JC2501SRS85476  
MOTO S/D 152FMH\*06127641\* ILEGIBLE (OXIDADO)  
MOTO 472BUC 4CY-001505 4CY-001505  
MOTO S/D 1P52FMH\*6182410\* \*8BMBSU00061004620\*  
MOTO S/D F1P52FMI\*81388860\* LWGXCHL5581003378  
MOTO 750DLY 1P52FMH\*71036943\* \*LF3XCH2G57A005053\*  
MOTO S/D LC1P150FMH\*08091483\* \*8A2XCHL78A0011639\*  
MOTO S/D 1P52FMH\*08012051\* \*LRYXCHLA586010495\*  
MOTO S/D A001828 8ELM15110AB001828  
MOTO S/D 1P52FMH\*51338212\* LF3XCGB015A002421\*  
MOTO 328CTX K1P52FMH\*060086669\* LYLXCGL5661013092  
MOTO S/D 1P52FMH\*083303468\* \*LSRXCHLD381304413\*  
MOTO S/D SDH157FMI-C\*13096476 \*LALPCJF8283014486\*  
MOTO S/D LC152FMHZ87000820 LCLXBHLG039100924  
MOTO S/D \*CL150FMG-2\*1D90179\* LCLXBGLD016000216  
MOTO S/D HA07EY429227 9C2HA0700YR429227  
MOTO S/D 1P52FMH\*06AD20P7 LJ4XCHLF961000410  
MOTO S/D 1F1P52FMH61391257\* LYLXCCL6671065108  
MOTO DAR548 HA07E67601660 8CHHA07007L000660  
MOTO S/D KB20\*39008854\* XLC2B8001073904481X  
MOTO S/D EB216476 CB218092  
MOTO S/D IB964096 \*9PABBAAA46A000449\*  
MOTO S/D JC41E1A002420 20099C2JC4110AR002420  
MOTO S/D O44580 ILEGIBLE (LIMADO)  
MOTO S/D ZS154FMI\*25500422 \*9PAABBB605A000435\*  
MOTO S/D 152FMH\*08427623\* LB7PCHLA082400721  
MOTO CBL102 4000159 8ELM111104B000159  
MOTO S/D 1P52FMH\*07300014\* LSRXCHLD771300959  
MOTO S/D LF1P50FM1\*81019670\* LSLXCHLH28A162410  
MOTO S/D KC08E58400430 9C2KCO8508R400430  
MOTO S/D SK162FMJ\*1000063549\* SK150LT-A9PDACBBB7A1294334  
MOTO S/D LC152FMH787000160 LCLXBHLG689100264  
MOTO S/D LC1P50FMH08062667\* LYLXCTL1681008197  
MOTO S/D DY80\*93097644 93112668  
MOTO S/D 156FHI295006774\* 8AHJ271258R000591  
MOTO S/D LF1P50FMH\*71139552\* LYLXCGL5971072672  
MOTO S/D HA07E65020429 9C2HA0760SR020429  
MOTO S/D JL1P50FMH\*06A069248\* LYLXCGL57610104427  
MOTO S/D 5DA157FM1\*6301173 \*LALPCJF8063200895\*  
MOTO S/D 1P50FMH\*06003098 LYLXCGL5461004049  
MOTO S/D 1P52FMH\*07080186 \*LRYXCHLA507060232\*  
MOTO S/D OJ153FMI\*2\*80001842\* LAWXEN0E58B249975  
MOTO S/D SDH157FMI\*63015608 \*LALPCJ8763206791\*  
MOTO S/D 152FMI\*08420552 \*LB7PCHLE682205726\*  
MOTO S/D 1P52FMH0830929 \*LSRXCHLD181303874\*  
MOTO 478SFD (S/A) KB25\*1200251 \*LC2B8102061200231\*  
MOTO S/D JC156FMI-TM81027530\* LJCFCLB881004773\*

MOTO S/D HA067E603500 83HHA07007L005598  
MOTO S/D KB20\*3805596\* XLC2B8001073901217\*  
MOTO S/D QJ153FMH-2\*70027988\* LAWXCHOA87B034196  
MOTO 921DAR 152FMH\*85BB4471 \*LCGXCHX2260802050\*  
MOTO S/D E410-TH108900 BE44A-TH108900  
MOTO S/D JC3013275362 9C2JC30103R275342  
MOTO S/D JL1P50FMH\*2003071744\* ILEGIBLE  
MOTO S/D 152FMH\*61173328\* LP7XCHL0860102920\*  
MOTO S/D JL1P50FMH\*10a319354\* \*8A2XCHLL3AA022252\*  
MOTO S/D ILEGIBLE #0782-DT  
MOTO S/D MX11225AE035885 NO SE ENCUENTRA  
MOTO S/D 162FMJ\*61346550\* \*LF37CK3A16D002398\*  
MOTO S/D 162FMJ\*70002912\* \*9PEAFF577LL00181\*  
MOTO S/D ILEGIBLE ILEGIBLE  
MOTO S/D LC156FM1A\*9P0130LI- LLCPCJLA8X1010806  
MOTO S/D Q1157FMI\*0680237195\* LAWPFJ00060717074  
MOTO S/D 96C10E 07447 96C11F00317  
MOTO S/D 152FMH\*06126127\* LB7PCHLB662064  
MOTO S/D KNI152FMI08050227\* LRPCHL0580006263  
MOTO S/D 37F0219SCM3SC0AN00091200313  
MOTO S/D LC152FMHFD367595 \*LLCXCHLL281070074\*  
MOTO 859DXR QJ157FMI\*8300320 LAWPEJ00088237423  
MOTO S/D ILEGIBLE (GASTADO) S/N  
MOTO S/D 1P52FMH\*12150151 \*LYLXCCL1X11008029\*  
MOTO S/D QJ253FMM+71015302\* LAWPFN3092B182694  
MOTO S/D 150FMG\*810084419\* ACKJ2408816100  
MOTO S/D JL1P50FMH\*044427791\* LYLXC6L5441005814  
MOTO S/D 1P52FMH\*A1014551\* \*EF3XCH264AA000211  
MOTO S/D HA07EI3016710 MODIFICADO  
MOTO DIX565 1P50FMH\*06162971 LYLXCGL5461049721  
MOTO S/D PBU015336 GOLPEADO  
MOTO S/D JC152FMH\*RD81000082\* \*LJCXCHLG681000039\*  
MOTO S/D 162FMJ\*08000461\* 1APC1520680000201\*  
MOTO S/D 152FMH\*6M173242\* \*LP7XCH0460102834\*  
MOTO S/D 152FMH\*06126659\* LB7PCHLE662062225  
MOTO S/D 9005506 8ELM361109B005506  
MOTO S/D 7007749 8ELH15110780077  
MOTO S/D 1P52FMH\*08010225 8A6MB5CAC8C90  
MOTO S/D 1P47FMD\*69068345\* \*LF3YCB3006D001522\*  
MOTO S/D 1P47FMHD\*10003849 \*LSRXCELAX12000130  
MOTO S/D ILEGIBLE TT16782 AUV927  
MOTO S/D EB958157 \*9PABBAAB35A000949\*  
MOTO S/D JL1P47FMD-3\*2001200967\* \*LSRXCERA612001579\*  
MOTO S/D EB002993 MNO SE ENCUENTRA  
MOTO S/D JC 152FMI\*RD81001071\* \*LJCXCHLG9810005583\*  
MOTO S/D JLP1P3PFMG\*2001004704\* \*LAAAXKBBC\*10001902\*  
MOTO S/D \*CL1P52FMH\*YA80101 LCLXBHLE3Y6002227  
MOTO CFD343 (S/A) SDH150FMG-265031025 \*LTMPCGB2665031198\*  
MOTO S/D KB203902651 \*LC2B8001063901386\*  
MOTO S/D HA07E6-5009922 9C2HA07605R009922  
MOTO S/D 1P52FM\*66090754\* \*LRYXCHLA366901233\*  
MOTO S/D JC147FMD-BHB61000122\* LJCPCDLCX61000063\*  
MOTO S/D LC152FMH\*DD450094\* \*LLCKCHLL061B21376\*  
MOTO S/D 50M603574 8A6M6SFQAP65040957

MOTO S/D 156FM-3\*2000000198\* \*LAAAANKJF860000218\*  
MOTO S/D 1P52FMI\*71065345\* 8A664PA270000026  
MOTO S/D QJ157FMI\*66051017 LAWPEJ0037B007809  
MOTO S/D 1P52FMH\*16508969\* \*LX8CH8017F002306\*  
MOTO S/D 6023328 LIMADO  
MOTO S/D 152FMH\*6117232\* LPYXCHLD1B0102824  
MOTO CSL876 HA07E65010417 9C2HA07605RQ6417  
MOTO S/D E337-0708872004PC6KE0420500290375\*  
MOTO S/D 5K150FMH\*0900015967\* SK110-A15PDABBBN59124  
MOTO S/D LC152FMHZ85000284 LCXBLE389100284  
MOTO S/D 1P52FMH\*66090824\* \*LRYXCHLA76690882\*  
MOTO S/D \*633883\* RH9HF125LXT124867  
MOTO S/D MX125AE032222 MX125A011533  
MOTO S/D 30P102175 LIMADO  
MOTO S/D 50AG68267 TR75057ANR340  
MOTO S/D 4CK-011865 CK-011835  
MOTO S/D JL1P39FMB\*2001004254\* \*LAAAXKBB1\*/\*10002282\*  
MOTO S/D KY1P50FMH\*06091328\* YLXCCL57100291  
MOTO S/D M152FMH07200008655\* \*LAEKX24708N000555\*  
MOTO S/D 1P50FMH\*6132074 LYLXCG516103219  
MOTO S/D 60622571 8ELM7211068062572  
MOTO S/D JC156FMITM81027506\* \*LJCFJLV88004933\*  
MOTO S/D ILEGIBLE AR125A-017562  
MOTO S/D 0105-04913 ILEGIBLE  
MOTO S/D 1P52FMI\*08200795 LB7XCAJLQHJLH462600795  
MOTO 539DAC 152FMI01060837 LB7PCHLF462060837  
MOTO S/D JC30E7071814 9C2JC30707R071814  
MOTO HWW778 152FMH\*VA222446\* \*LLCX4NCJ8B0C00143\*  
MOTO S/D LF1P50FMH\*81140230\* LYLXCG5081117810  
MOTO S/D 1P52FMHA1033004 \*LF3XCH2C3AA001249\*  
MOTO 654EDK NDO7E85L1265 9C2ND7008R511265  
MOTO S/D YG1P52FMH\*AJ003276\* \*LY4YXBH04A1003276\*  
MOTO S/D 1P52FMH\*6112577 8A6M550AA65053670  
MOTO GYR537 IP50FMI-\*A1239355\* LYLXCHL58B1153381  
MOTO S/D 5DH150FM6-2KA5804048 LIMADO  
MOTO S/D M152FMH\*381368 \*8BMVBU0001000911\*  
MOTO S/D CP05399 Z03503  
MOTO 767DYJ 162FMJ\*80217420\* \*LEAPCK2058B901144\*  
MOTO S/D 156FME66010035 \*LRYPCJL6866900038\*  
MOTO S/D QJ153FMH-2\*677001729\* NO SE ENCUENTRA  
MOTO S/D C70E-G120156 N/S  
MOTO 640DLY 161FMJ\*71262482 \*LF3PCXD0870010114\*  
MOTO S/D 1000740 M061001B000740  
MOTO S/D LF1P50FMH\*81064114\* \*SRXCHLD48A424852\*  
MOTO 899HMJ CJ30E14057888 9C2JC30104R057888  
MOTO 784DXR 1P52FMH\*080000170\* 8A2XCHLA18A002889\*  
MOTO 576DAR ZS150FMH\*16711924\* N/S  
MOTO 976DLY LC1P50FMH\*08045553 \*A2XCHRM38A001162\*  
MOTO S/D IC152FMHDXD389742 \*LLCXCHLL571B71577\*  
MOTO CMG487 1P52FMH\*6409825\* ILEGIBLE  
MOTO 596GGU LF1P50FMH81079275\* 8EGSMASHF8GC00474  
MOTO S/D 1P50FMH\*05100732\* LYLXCG5951944237  
MOTO 773DAR LF1P50FM71028396 LWGXCHL4732014265  
MOTO S/D 162FMJ\*09B12847\* LHJYCKLA192613180

MOTO 981DKE 1P50FMH\*06112139\* LIMADO  
MOTO 642HUZ KN152FMH\*11050117\* \*8E71CDA79B0024752\*  
MOTO 127HRU QJ157FMI\*66050839\* LAWPEJ00X7B007841  
MOTO S/D 1225498760 3.56584E+12  
MOTO S/D LC152FMHxD366130 LLCXCHLL471B71344  
MOTO DAR660 1LP50FMH\*61285368\* LYLXJL5361046910  
MOTO S/D 1P52FMH6601468 \*LRYXCHLA666901196  
MOTO S/D 50A608717 N/S  
MOTO S/D KN152FMIP2A11503107 \*1RYPCHLY1A0018681\*  
MOTO S/D DK50XB 112901 DK50XF1217554  
MOTO S/D 1P52FMH08A03979\* ILEGIBLE  
MOTO S/D SK150FMH\*0800044415\* SK110-A2 9PDABBBU781197908  
MOTO S/D LF1P52FMH71278506 LYLXCOL5371067460  
MOTO 386GNU IP52FMH\*08012901\* \*LRYX0HL8486010304\*  
MOTO S/D 1P52FMH08061576 LPYXCH9J3809C1533\*  
MOTO S/D 162FMJ\*62100134\* \*LBXPCKCM27X040019\*  
MOTO S/D IP52FMH\*71051207\* LYLXCG15271071167  
MOTO S/D IP52FMH\*07060169\* \*LRYXCHLA807060208\*  
MOTO 565DUS 5017901SIGUIENTE ILEGIBLE 8ELM9 1105B017919  
MOTO S/D HW150FMJ\*97019304\* \*BX100K97080087\*  
MOTO 852BCL NO SE ENCUENTRA 8AHJ39050VR001021  
MOTO DAR827 QJ150FMH\*80006348\* ILEGIBLE  
MOTO S/D JC30E7 6801438 9C2JC30706R801438  
MOTO S/D SDM152FM265127379 \*LTMPCGB2X65150081\*  
MOTO S/D ILEGIBLE ILEGIBLE  
MOTO DXR563 LF1P50FMH\*81051405\* LSRXCHLD88A316038  
MOTO S/D JC25EV448859C2JC250V9C2JC250V  
MOTO S/D OOA10E 11062 OOA11F00168  
MOTO S/D KC08E16500102 9C2KC08106R500102  
MOTO S/D SDH157FMI-\*63022790\* \*LALPCJF816E257980\*  
MOTO S/D 1P52FMH\*76090473\* \*LRYXCHLAX70900162  
MOTO 152FMH\*11A01767\* LHJXCHLA0B2718812  
MOTO DLY720 LF1P50FMH\*71028361\* LWGXCHL4672014230  
MOTO LC152FMH Z87000116 LCLXBHLG889100222  
MOTO 854DAR 5M0701794 N/S  
MOTO S/D HA07E1 5037343 9C2HA07105R037343  
MOTO S/D SDH150FMG-275808853 8CHPCGB208L000727  
MOTO S/D ADULTERADO LCAXCH50X8B903H3\*  
MOTO S/D 152FMH70380559 LP7XCHL0070000251  
MOTO S/D 7031491 \*LUHPCM87070071262\*  
MOTO 780DLY LF1P50FMH-81024642 LSRXCHLF58A205058  
MOTO 956DLY ZS156FMH16811036\* \*LZSXCHLF461017647\*  
MOTO DAR741 JL1P50FMH\*61285281\* LYLXCG15861046823  
MOTO S/D LE50FM\*9912132145\* \*9912101611\*  
MOTO S/D 150FM-3\*2007020256\* \*LAAXKHAB9770002262\*  
MOTO 747EQT 162FMJ8021714P \*LEAPCK2068B901055\*  
MOTO S/D 1P52FMH\*07060406 \*LRYXCHLAX07060386\*  
MOTO S/D 6041483 8ELM0515068041483  
MOTO 907HJF A032441 8ELM24110AB032441  
MOTO S/D LC152FMHZ85000857 LCLXBHLE289100857  
MOTO EPK565 7077011 8ELM0311007B077011  
MOTO 461DKC LC1P50FMH\*08048856 \*8A2XCHLX08A000903\*  
MOTO 172CJM 157FM1-L\*50006126\* \*LAAACJLR850006126\*  
MOTO S/D JC152FMH\*RT81001P26 \*LJCKCHLG481000847\*

MOTO S/D 1P50FMH09202594 \*8A2XCHLL49A007027\*  
MOTO S/D 1P52FMH\*91000927 8AHJ221109R003577  
MOTO S/D DK50XE1143619 DK50XC1237754  
MOTO S/D 1P52FMH7302225 \*LSRXCHLD071303170\*  
MOTO S/D 12Z331597 3ZG01599  
MOTO S/D 1P52FMH651323814 \*8BMBSU00061003302\*  
MOTO 697CXR 153FMI-2-67047127 LAWXEH0AX6B298258  
MOTO S/D DK50XE1121257 DK50XE1216788  
MOTO 1P52FMH\*08303566\* \*LSRXCHLD3811304511\*  
MOTO 184GVA 1P52FMH\*A115343Z\* N/S  
MOTO S/D M152FM1\*0805000447\* \*8D20TQ020091000293\*  
MOTO S/D 1P52FMH\*80401278\* \*LEAXCH5098B902896  
MOTO S/D 152FMH\*09444834 \*8BPC40LB7AC008352\*  
MOTO 642BGN 1P52FMH\*71006252\* \*LF3XCGB067B000614\*  
MOTO S/D 1P52FMH\*07080872 \*LRIXCHLA107060793\*  
MOTO S/D JL1P50FMH\*06A088251\* ILEGIBLE  
MOTO S/D LC152FMH-XD389782 \*LLCXCHLL771B71516\*  
MOTO S/D BORRADO 9C2H07002R007992  
MOTO 113HRU JC1P52FMH\*RJ91038415 \*8BJXCHL1191002732\*  
MOTO S/D Z5152FMH\*84700889\* N/S  
MOTO S/D 162FMJ\*B0100136\* \*8020KM030C1000676\*  
MOTO S/D 150FM-2\*2007000942\* N/S  
MOTO CXR560 JL1P52FMH\*1005200755\* 8CVXCH8AXAA006825  
MOTO S/D 50LG18655 ARMADO  
MOTO S/D JC25E-X154793 9C2JC2500XR154793  
MOTO 253AQA JC30E22004460 9C2JC30202R004460  
MOTO S/D 157FMJ\*06060526\* \*LAACJLR7660008516\*  
MOTO 506DLY KB20\*3908770\* ù\*LC2B8001073904506\*  
MOTO 1P52FMH\*712730792 LF3XCGB0XILEGIBLE  
MOTO 565AWE DB001E2200892 ILEGIBLE  
MOTO FR50-H9261 KM4BA11A73 1119367  
MOTO 622DLY 150FM-3\*2007001036\* N/S  
MOTO S/D HA07E67600468 8CHHA07007L000831  
MOTO 975BXK 0B010E 2408986 ST70-6604428  
MOTO ILEGIBLE \*LRYPCKL02A0001962\*  
MOTO 1P50FMH\*06030370 LYLXCG1X61001105  
MOTO 162FMJ\*81099187 \*LF3YJK3A68000J727\*  
MOTO 228BGN JC25E-W086354 9C2JC250WVR086354  
MOTO 833DAR 1P50FMH\*06118420\* LYEXGCL57610201156  
MOTO S/D ADULTERADO LYLXCG151009899  
MOTO S/D 4B20\*3900539\* \*LC2B800105390021  
MOTO S/D UJ157FM1\*8300925 LAWPEJ098B250343  
MOTO S/D LC1P50FMH\*0115194\* LC6XCHX2560800759  
MOTO S/D 1P52FMH\*0730234\* \*LSRXCHLD471303267\*  
MOTO S/D 1P52FMH\*08304454 \*LSRXCHLE7811305399\*  
MOTO 718EPK LF156FM1\*71189896\* \*LAZPCJLT371012206\*  
MOTO S/D 1P52FMH\*1626713\* 8DYC11071BV011973  
MOTO S/D 5026067 NO SE ENCUENTRA  
MOTO 264GTH 5022733 8ELM071505B022733  
MOTO S/D 162FMJ\*10197462\* \*9PEAGFE511E51BL400618\*  
MOTO S/D 162FMJ\*09009660 LHJYCKLAX92578098  
MOTO S/D JLT150FM1\*10D0260213 \*LAAACJLR2A5080851  
MOTO S/D 1P52FMH\*06110501\* LSRXCHLC87A115116  
MOTO S/D ZS161FM\*57800058\* \*9RAACBBE78A000293\*



MOTO S/D 1P52FMH\*10500202\* \*LBXXCH9JXA0A70338\*  
MOTO 702DBH 161FMJ-7103054 \*LF3PCKD087D002207\*  
MOTO S/D DY90\*339198\* \*332221\*  
MOTO S/D ADULTERADO ADULTERADO  
MOTO S/D \*91624\* LIMADO  
MOTO S/D F13551P54FMI\*08E01259\* LAPXCJLC480002428  
MOTO S/D DJ152FMH\*06043048\* LCLXBHLE369000358\*  
MOTO S/D RG-SF20\*1900847 RFBSF20AF19000768  
MOTO S/D 152FMH85BB1359 8ELM121104B002607  
MOTO S/D C9OE-2011752 N/S  
MOTO 880IMQ KL152FMH11093281 \*LRYPCHL28B00775313  
MOTO S/D C010087 8ELM32125CB010087  
MOTO 510DXR LF1P50FFMH\*81072071\* LWGXCHL41B2023046  
MOTO 817EPK SDH150FMG85830890 8CHPCGB219L002661  
MOTO 580DXR 1P52FMH\*07B1482\* \*LHJYCHLA078801054\*  
MOTO S/D SDH150FMG65073290 \*LTMPCEB2455077628\*  
MOTO S/D BORRADO N/S  
MOTO 781DLY SDH150FM-G265106633\* \*LTMPCEB29065111774\*  
MOTO 459AUY AF18E-5004628 JH2AF2725NK004117  
MOTO E104-1D568875 MHDRC100PWQ345516  
MOTO S/D 152FMH06051203 \*LHJXCHLAX60493025\*  
MOTO S/D 2007020320 \*LAAXKHAB770002177\*  
MOTO S/D CZ-CAGIV487.3.03\*009996\* 48702786  
MOTO S/D HA07E-W1011S4 9C2HA070WWR101184  
MOTO S/D RPM012240 ADULTERADO  
MOTO S/D LIMADO N/S  
MOTO S/D 163FML211\*92028638\* \*LF3YCM2069D002681\*  
MOTO S/D 1P52FMH12A194995 8CVXCH2G9CA040528  
MOTO S/D KL152FMH\*09050459\* \*MRYPCHL2090004214\*  
MOTO IP47FMDG1076576 N/S  
MOTO 603DLY SDH150FMG75808437 8CHPCEB208N001025  
MOTO S/D 1P50FMH09601160 \*8A2XCHLX8BA012275\*  
MOTO S/D 1P50FMH06030820 LYLXCG17861001555  
MOTO S/D 1P50FMH06030743 LYLXCG11561001478  
MOTO S/D 1P50FMH06109950 LYLXCG11161001820  
MOTO 907IMQ 1P52FMH26035828 8A6MBSACDC850035  
MOTO S/D HA07E6-5006123 9C2HHA07605R006123  
MOTO 368CXZ 1P52FMH\*61107240\* \*LF3XCGB096A035846\*  
MOTO 265DAR E3B83044118203 9C6KE044040044348  
MOTO 670GAU 152FMI6H73369 LP7XCHL0060102961  
MOTO 558FAD KN152FMI 92\*91236588 \*NRIPCHLI390006236\*  
MOTO 408DKC QJ053FMH-2\*70108118\* LAWXEHOE28B202936  
MOTO 533GYR 1P50FMH06030460 LYLXCG11461001195  
CUATRICICLOS/D Z5161FMJ2B250067 N/S  
MOTO S/D 150FM3200400244 LAAAXKH0X\*/40001686\*  
MOTO S/D KB206302017\*LC2B8002085001188\*  
MOTO 211GAK QJ162FMJ8543474 \*8CWFL0150A1RB2023\*  
MOTO S/D 7032458 8ELM162007B032458  
MOTO S/D JC30E12131766 KM4SF11A7N1203722  
MOTO S/D QJ153FMH-2\*80004978\* LAWXCH0E88B301793  
MOTO S/D 1P50FMHB1042165 ILEGIBLE  
MOTO S/D 162FMJ\*80403340\* \*LEAPCK2058B901919\*  
MOTO 968DAR 152FMH\*06103519\* RB7PCHLA562062388  
MOTO SDH150FMG-2\*55151810\* \*LTMPCEB2655152215\*

MOTO S/D IA07E1020922 9C2HA07001R020922  
MOTO 549 HEV JC1P52FMH\*RJ91020564\* \*8BJXCHL1191000922\*  
MOTO S/D 1P52FMLH1109200697 8CVXCH8A6BA016866  
MOTO S/D B026841 8ELM15110BB026841  
MOTO S/D 50A601580 ARMADO  
MOTO S/D JL1P50FMH\*20ILEGIBLE LYLXCGL1P31000071  
MOTO S/D 152FMH\*094333991\* LR7PCHLB392109883  
MOTO S/D 180FM32008029156 \*8A2XCHLZ5AA005165\*  
MOTO 201HYC 1P52FMIC7608331 NO SE ENCUENTRA  
MOTO 534HHW KN165FMJ92\*B1055078\* LRYC CKL04B0055699\*  
MOTO S/D 150FM-3\*2008028236\* ILEGIBLE  
MOTO 810DAR JL1T50FMH61285321 LYLXCGL5961045863  
MOTO S/D \*6C001499\* N/S  
MOTO S/D \*621627\* RH9HD150LY1010147  
MOTO S/D 152FMI08420587 \*LB7PCHLE882205761\*  
MOTO S/D QJ1E50FMG 81000478 LAWPAG0M38T219660  
MOTO 200GUO 1P52FMHA057656 \*LXYXCHL023B0509790\*  
MOTO S/D 152FMH06126674 LB7PCHLE262062240  
MOTO 971DVS 1P52FMH\*08010765\* 8A6MBSAC7C900931  
MOTO S/D 1P50FMH\*06006123\* LYLXCGL5461005332  
MOTO S/D 6029928 8LM211255B029928  
MOTO S/D 150FM-3\*2009007338\* \*8A2XCHRM29A007892\*  
MOTO S/D 1P52FMH\*62130014 \*8BMBSQ00061005314\*  
MOTO S/D LF1P50FMH\*81033565\* LSRXCHL078A310800  
MOTO S/D LF1P50FMH\*71128493\* LYLXCGL5171069491  
MOTO S/D QJ157FMI\*8611782\* LBBPEJJ018B356860  
MOTO S/D LF1P50FMH71317100 LYLXCGL5471087841  
MOTO S/D 152FMH3603730 \*LRPXCHLC7C3603680\*  
MOTO S/D 161FM220080042037 \*LAAECKLA880000445\*  
MOTO S/D KN152FMI11091416 \*8E71CDA73C0000514\*  
MOTO 879EPK 150FM32009004557 \*8A2XCHLM29A006497\*  
MOTO S/D 50LE1677 N/S  
MOTO 546GYR S152FMH18879 \*LZSXCHLM071007149\*  
MOTO S/D 150FMG 81008411 \*LLCXCHLLX81070100\*  
MOTO S/D 161FMJ81012483 \*LF3PCK00880002242\*  
MOTO S/D 1P52FMH-08062513 \*LBXXCH9J28090\*  
MOTO S/D QJ153FMH-2\*67155118\* LAWXEH0E06B795290  
MOTO S/D 1P50FMG-B000279 8A6MLZCZCS000019  
MOTO 898DXR 1P52FMH-07801193 \*LHJYCHLA47B8010\*  
MOTO 443EUT LF1P52FMI\*91334654\* LWGXCHL59A1005407  
MOTO 554DVS YG1P52FMH\*80001072 N/S  
MOTO S/D JC150FMI-018100507 LJCFCJLV681000916\*  
MOTO 648DTL QJ157FMF-8004152 LAWPFJ0C68B274521  
MOTO S/D LIMADO LIMADO  
MOTO S/D HA07E14015347 9C2HA07104R01340  
MOTO 212HCJ 1P52FMH-0A600891 8A6MBSVCZBC501938  
MOTO 076CFD \*626829\* RH9HF125LX1068691  
MOTO S/D 1P50FMH\*06030498\* LYLXCGL1866104233  
MOTO 106EVZ LC1P50FMH-080442253 \*8A2XCHLM28A000391\*  
MOTO 390GNV 162FMJ\*9B07012\* LAJYCKLA692591012  
MOTO S/D 1P47FMD\*51362037\* N/S  
MOTO 559DAR 1P50FMH\*06030654\* YLXCGL1661001389  
MOTO S/D EB005772 N/S  
MOTO S/D 162FMJ\*11E16743\* LHJYCKLA9B2755617

MOTO S/D 1P52FMH1129900 \*9PEACDE40BL301683\*  
MOTO S/D 152FMH09001876 LHJXCHLA592560039  
MOTO S/D 1P52FMH-6123741 LSRXCHLC561200316  
MOTO S/D LF1P52FNH-B12251007 ILEGIBLE  
MOTO 416ISN A0901906 \*8BPC4DLB3BC087655\*  
MOTO S/D 97010E-08650 N/S  
MOTO 211ELY JC30E8-503719 9C2JD20180R505719  
MOTO 682DXR 162FMJ\*08006960 LHJPCKL082520821  
MOTO 082CBL 162FMJ-2A-13038576 \*8BPE4KLN5AC001552\*  
MOTO S/D 162FMH-856B0676 \*LP7XHL0770000509\*  
MOTO S/D 1P50FM\*97006685\* 0M100\*97028117\*  
MOTO 552DAR 1P50FMH\*0600821\* LYLXCGL1861000311  
MOTO S/D JD17E-X100602 9C2JD1700XR100602  
MOTO S/D EB002396 N/S  
MOTO 795DAR JL1P50FMH\*06A09202\* LYLXCCL5951010381  
MOTO 493CFD JA04E2-6866013 92JA0420GR8660  
MOTO S/D 1P52FMH\*ZC032928 8A6ZBSH0ZCC501747  
MOTO S/D SDH150FMG-2\*55025010\* \*L1MPCG58455027178\*  
MOTO S/D 8020626 8ELM151108B020626  
MOTO S/D 1P52\*12150233\* \*LYLXCGL1811008174\*  
MOTO S/D BORRADO BORRADO  
MOTO 092AUY 12ZBE1425 3ZB00Z1  
MOTO S/D 1P52FMH\*06110060\* N/S  
MOTO S/D QJ153FMH-2\*67162303\* LAWXEH0E26B86  
MOTO S/D 1P52FMH\*0B416967 LSRXCHLE6BC160540  
MOTO S/D LC1P50FMH-0804430 \*8A2XCHLM88A0007752\*  
MOTO 613GIF SDH157FMI-C\*93405602 8CHPCJF81AL000345  
MOTO S/D 152FMH-07110994 LB7PCHLF372000260  
MOTO S/D 25163FML\*18302737 \*LZSJCL0781003187\*  
MOTO 111CPC JC1P50-10143723 LYLXCGL5851014341  
MOTO S/D 152FMHVA13249 LLCX4NCJ380101719  
MOTO 034HRU LC152FMH\*JA037847\* 8A6MHSW2ZCC50057  
MOTO 903DLY LFP50FMH\*71461453\* LSRXQLK27A629373  
MOTO S/D E382E-144528 2007 9C6KE092080145499  
MOTO S/D 1L1615757 1L1615757  
MOTO 969DXR LF1P50FMH\*91022941\* \*8A2XCHLL19A004442\*  
MOTO 195IOT 163FM2-2MP\*C2003084\* \*3PCMGC3B000369\*  
MOTO 814BGN DK50XE1114074 DK50XF1208604  
MOTO S/D 1P52FMHX71059824\* \*LEXCH2G57A008244\*  
MOTO S/D JC30E8 4014481 9C2JD20104R014481  
MOTO S/D QJ157FMI\*68020131\* LAWPEJ0017B007513  
MOTO S/D 1P50FMH\*06150195\* LYXC0576104353  
MOTO 762EXE KB20\*3909836\* \*LC2B8001083900587\*  
MOTO 958IIT 1P52FMH-C1025106 \*LF3XCH2G3CA008317\*  
MOTO 404HFF LF1P50FMH\*B17387\* 80X13MASHFBGC11527  
MOTO 123CFD DK50XE-1161767 DK50XF1512857  
MOTO S/D JC30E8-1014768 9C2JD20104R017468  
MOTO S/D LC152FMHSA9700381 LCLXBHLG2A9100381  
MOTO S/D JL1P50FMH\*05B004073\* ILEGIBLE  
MOTO S/D QJ153FMH-2\*67129805\* LIMADO  
MOTO S/D 1P52FMH41930702 16C93H84378  
MOTO 173EWI Z5150FMH\*168125147\* BORRADO  
MOTO S/D SK162FMJ\*1000088116\* STAR150 9PDACBBR6B1327660  
MOTO 665GXN 152FMH\*061125238\* LB7PCHLB662063638

MOTO S/D 1P52FMH\*OAA01738\* 8A6MBSVCZBC501785  
MOTO 888BGN 1309046 1309046  
MOTO S/D 1P52FMHA27005313 CRPCKLG3A2705693  
MOTO 141CCJ 1P50FM\*97011290 ILEGIBLE  
MOTO 792EPK ZS152FMH\*17A18897\* \*LZSXCHLH271007167\*  
MOTO 191GBU SDH150FMG-2A5025490\* \*LTMPCGB2XA5802335\*  
MOTO 852DLY SDH150FMG-2\*A5827589\* 8CHPCGB21BL004351  
MOTO S/D QJ153FMH-2\*67000299 LAWXEH0E66B010562  
MOTO S/D 161FMH\*B2010017\* \*8BMBKT000B1004648\*  
MOTO S/D QJ157FMI8640641 \*8CWRX0125A1RX1365\*  
MOTO S/D 1P52FMH\*66091445\* \*LRYXCHLA266900871\*  
MOTO 302JRU KT1P52FMH\*E001484\* \*8A2XCHLL8DA063660\*  
MOTO S/D JC30EL2112503 9C2JC30202R112503  
MOTO 872GFC 152FMH09475775 LB7PCHLE992210503  
MOTO S/D \*JCE5009346\* \*2005\*\*94J2XDCE55M00420  
MOTO 573DAR QJ153FMH-2\*67047099\* LAWXEHOA96B298154  
MOTO S/D 1P52FMH\*08AD3669\* LJ4XCHLG481011676  
MOTO 246XNG KD05E2A009338 20099C2KD0520AR009558  
MOTO 901BGI Z8156FMI-2A\*7906489\* 608509  
MOTO S/D 1P50FMH05112682 LXLXCG5X61001317  
MOTO S/D 1P52FMH08AD44094 LJ4XCHLJ281012101  
MOTO S/D HA07EG7611641 8CHHA07007L012490  
MOTO S/D 152FMJ\*B6000005\* \*LRPNCKLK5B6000302\*  
MOTO 679DAR SDH150FMG-2\*65035838\* LTMPCGB2365 ILEGIBLE  
MOTO 438GIK 1P52FMH\*A1062163\* LAWXEH0A088305155  
MOTO S/D 157FMI\*0B021728\* \*LAAAC0LL3B1120590\*  
MOTO 593ITM 167FMLC6603899 \*LRPNMLJ6C6603912  
MOTO 631IYV 162FMJ\*8C061812 XY150-NTPDACBBS481199305  
MOTO S/D LC1P50FMH\*08009520\* LYLXCG5481117390  
MOTO 967DLY 1P52FMH71773267 \*LF3XCGB007A039964\*  
MOTO 941JTI FL1P50FMH\*81121591\* 8EGSMASHT8GC01830  
MOTO S/D 150FMO-2006004348 LAAAXKHG5\*\*60002537\*  
MOTO S/D 1P52FMHZC013240 8A6XCGB04CA800375  
MOTO S/D RF1P50FMH\*B1148080\* 8CXSMASHFBGP09448  
MOTO 845DXR 1P52FMI71108946 \*LF3XCH2G87A009582\*  
MOTO S/D SDH150FMG-2\*8582279\* 8CHPCGB208L028725  
MOTO S/D 162FMJ09002143 LHJPCCLA592556294  
MOTO S/D 152FMH0746219 LB7PCHLE772203370  
MOTO S/D XYP52FMH06100004 \*8A2XCHLA37A000257\*  
MOTO S/D BORRADO BORRADO  
MOTO S/D 152FMH\*08427210\* LB7PCHLE082208606  
MOTO S/D 1P52FMH\*80401060\* N/S  
MOTO S/D 1P52FMJA07605525 80YC11242BV000641  
MOTO 617JNA D021596 8ELM151100B021596  
MOTO 866IAR 1P52FMH\*OA775629\* \*8A2XCHLX2BA018472\*  
MOTO 722DNY 161FMJ\*61184696\* \*LF3PCKD076D003783\*  
MOTO 551EPK LF1P52FMI\*81294197\* LWGXCHL5081002154  
MOTO 489IBI 1P52FMH\*A1812446\* \*LSRXCHLB2A1813929\*  
MOTO 533GRO 162FMJA2510843 80YC51494AV00Z416  
MOTO S/D KB22\*1004725\* \*8CMKMC110C1C11915\*  
MOTO S/D LC152FMHZ870001120 \*LSRXCHLD581303408\*  
MOTO 894EQY 1P52FMH\*81280728\* LF3XCH8A18A003501  
MOTO 609KDX 1P50FMH-A\*13A017010\* 8CVXCH2G8DA058097  
MOTO S/D 1P52FMH\*\*1032543\* LF3XCH2G4AA001342\*

MOTO S/D ZS150FMH16630280 N/S  
MOTO 299GME 162FMJ80403316 \*LEAPCK2078B901758\*  
MOTO 373DEN JM1P50FMH\*61285940 LYLXCGL5261047482  
MOTO 932IMQ 157FMI\*06081421\* LAAJJCJLB677000421  
MOTO S/D 9005296 8ELM1511098005296  
MOTO S/D JL1P52FMH\*1109200499\* 3CVXCH8A4BA016736  
MOTO S/D A032017 8ELM12110AB032017  
MOTO S/D 162FMI\*A2705503\* LSRPCKLG8A2705883  
MOTO S/D KB20\*3910704\* XLC2B800108390132CX  
MOTO 793EPK 152FMH\*08427185\* LB7PCHLEX82208581  
MOTO S/D ECK162FMJ\*0900016463\* SK150-DEP9PDACBBAX91243767  
MOTO S/D EC3PE0250062 20099C6KE121090025050  
MOTO 075HRU LF1P52FMIB1121283 8CXREV125B0001912  
MOTO 873DLY QJ153FMH-2\*70087918\* LAWXEH0EX8B171080  
MOTO S/D 6021681 8ELM200706B021681  
MOTO S/D 1P52FMH81224971 \*LF3XCGB008A007467\*  
MOTO 125JRU JC41E19056863 2009962JC41109R056863  
MOTO 597IZH E3L6E-236687 8C6KE198000003820  
MOTO 049CFD 036543KIE-RA KIF-RA035949  
MOTO S/D SDH150FMC\*85801756\* 8CHPCGB208LO16923  
MOTO S/D 50M608197 280100050  
MOTO 183GKG 1P52FMI\*A7504633\* \*LSRXSJME0A7504359\*  
MOTO S/D C90E-2-153678 C90-5701761  
MOTO S/D JCC5007760\* \*2005\*\*94J2XDCE55M005959\*  
MOTO 700DXR QJ153FMH-280001158 LAWXEH0A78B238828  
MOTO 952DKE 1P52FMH714493499 \*LS3XTGB027B004627\*  
MOTO 574HV0 KM182FMJ92\*B1383995\* \*LRYPCKL02B0046224\*  
MOTO 557HBT B019624 8ELM15110BB019624  
MOTO 417GIK SDH157FMI\*C\*73021873\* \*LALPCJF8573067052\*  
MOTO 133GJM KN182FMJ92\*A1090153\* \*LRYPCKL05A0013488\*  
MOTO S/D DK50X1146545 DK50XF1180443  
MOTO S/D DK50XE 1167243 DK50XF1516834  
MOTO 189CBL 5016989 8ELM111105B01698 SGTES LIMADO  
MOTO 687JCV 1P52FMIC6609038 8DYCX10770V003916  
MOTO 166GVA \*LF1P50FMH\*A1319492\* 8SXSMASHFBGT10072  
MOTO S/D 162FMJ10B37244 LHJYCKLA2A2679804  
MOTO 272JDM JC30E511014989 9C2JC30501R014989  
MOTO 737HIX KC08E2B580776 8CHK082OEL000691  
MOTO S/D DK50XE1164909 DK50XF1514845  
MOTO S/D SK162FMJ1100012166 SK150-MPSPDACBBB3B1344986  
MOTO S/D 162FMJ08001820 \*LEAPCK2088000201  
MOTO S/D LS152FMH285000958 \*LSLXBHLE889100958  
MOTO S/D JL152FMI-5\*10A246641 \*LAAATJLR4A5080575\*  
MOTO S/D JL156FMI10A246649 \*LAAASJLR3A5080647\*  
MOTO S/D 4CK-023469 4CK-023469  
MOTO 231CZX G318E-025772 9C6KG014060008245  
MOTO S/D 152FMH\*70380666\* LP7XCHL0170000361  
MOTO 863IAR 162FMJ10B207951 LHJYCKLAXA2649174  
MOTO S/D 5AV-635952 LAPXCHLA460038558  
MOTO S/D JL1P50FMH054240420 LWGXCHL4852002724  
MOTO 278DEY SDH157FMI-C\*73016016\* \*LALPCJF817E05812E\*  
MOTO 552FAD NO SE IDENTIFICA 8\*8BPC40LB3AC004430\*  
MOTO S/D JC30E84013619 9CJD20104R013819  
MOTO 743CXR SDH157FMI73028856 \*LALPCJF8473091021\*

MOTO 729EPK 161FMJ61092094 \*LF3PCKD096D002240\*  
MOTO S/D LC152FMHDD415495 LIMADO  
MOTO S/D HAOEFEY442101 9C2HA0710YR442101  
MOTO S/D JC3027403422 9C2JC30705R403422  
MOTO S/D 1P52FMHB1013564 8AHJ22110BR005508  
MOTO S/D LF1P50FMHA1060181 LYLXCG59A1148074  
MOTO S/D BORRADO \*LF3PCKD0088D000622\*  
MOTO 039IDA 1P50FMH\*0B411640\* 8CXSMASHFBGC15946  
MOTO S/D ZS150FMH\*15503507\* NO SE ENCUENTRA  
MOTO S/D 162FMJ\*12A06960\* LHJPCKLA7D2892394  
MOTO 298DKS 7026098 8ELM071507B026090  
MOTO 491GIK 1P52FMH90107080 \*LXFXCHPA09B901288\*  
MOTO 186CFD 150FM-32004000476 \*LAAAXKH0640000A06  
MOTO S/D B028270  
MOTO 874IAR 167FML\*C6603938\*  
MOTO S/D 150FMG-10A01144  
MOTO 826HMU B017828  
MOTO S/D 162FMJ\*81567342\* \*9PEAE516LGY0548\*  
MOTO 752HWW 1P52FMHB10130558 8AHJ22110BR005569  
MOTO S/D QJ153FMH-2\*70122349\* LAWXEH0E889217506  
MOTO S/D 152FMJ\*50008582 \*9PAACB55A000036\*  
MOTO S/D 1P520FMH06101959 LYLXCG5661007678  
MOTO 856EPK HA07E6501532E 9C2HA07605R015326  
MOTO S/D 1P50FMH-A\*12A261753\* 8CVXCH2G4DA051664  
MOTO S/D JL1P52FMH\*B05202129\* 8CVXCH8A9DA036922  
MOTO S/D 65444 \*8DDG102218A110759\*  
MOTO 346CFD D013225 8ELM422500B013225  
MOTO 493IND 1P52FMH-A1149065 \*LF3XCGB0XAA010026\*  
MOTO S/D JL1P50FMH1109200574 8CVXCH8A2BA016797  
MOTO 423DWF DA30\*2800161\* \*RFBAF30BB72800158  
MOTO 512DXR 163FML\*FJ220731\* 8A6YCM20Z8C000079  
MOTO 196GKG JA04E18025684 9C2JA04108R025684  
MOTO 548DAR HA07EG-7604157 8CHHA07007L004122  
MOTO S/D JC30E8-4013000 9C2J020104R013000  
MOTO S/D 152FMH60965441 \*LP7XCHL0560102549\*  
MOTO S/D 1P52FMH\*0A026121\* 8CXSMASHSEBS01194  
MOTO S/D JC30E12P44483 9C2JC30102R144483  
MOTO S/D JL1P52FME-105200813 8CBXCH8A6BA013160  
MOTO 348HCI 1P52FMH\*76505025\* \*LX8XCH8057F000980\*  
MOTO S/D 150FM-3\*2007018284\* PINTADO  
MOTO 739DAR LF1P50FMH\*71028342\* LWGXCHL4272014211  
MOTO 338BYR 147FMI-98011324 BORRADO  
MOTO 455DKC 1P52FMHA1002677 8BKXCHGGA0A000044  
MOTO S/D LE50FM\*9912141946\* \*9912120532  
MOTO 727EQY 162FMJ08203328 \*LSRPCKLC382103789\*  
MOTO S/D SDH150FMGA5824014 8CHPCGB21BL002592  
MOTO 723BNN MD34E-5012632 9C2MD34005R012632  
MOTO S/D QJ157FMI68002685 LAWPEJ0CA6C87530  
MOTO S/D M152FMI\*0805001002 \*8020TU02091000311\*  
MOTO S/D 152FMHOA105527 \*9PAABBBRSAA001003\*  
MOTO S/D SDH150FMG-255124985 \*LTMPCGB2655125192\*  
MOTO S/D E385E-027140 20079C6KE093080027153  
MOTO S/D 162FMI60008164 NO SE ENCUENTRA  
MOTO S/D JC60E9431248 9C2JD20204R031248

MOTO 118CRY 1P50FMH06006309 LYLXCGL5761005518  
MOTO 266ELY 162FMJD2636778 9C2JD080TTR005341  
MOTO S/D JC152FMHRD81001135\* \*LJCXCHLG181000353\*  
MOTO S/D 162FMJ1B982288 LHJYCKLA1B2732364  
MOTO 596EPK 152FMH07110765 NO SE ENCUENTRA  
MOTO 864DAR 152FMH60965423 \*LP7XCHL0860102531\*  
MOTO S/D KN152FMHE0200611 LIMADO  
MOTO S/D 70M508843 DK50XF1507901  
MOTO S/D 152FMH\*07201948\* LB7PCHLE672201948  
MOTO S/D 5AV-500190 LAPXCHLA65A000323  
MOTO S/D JL1P50FMH06A17117 LYLXCGL5161030849  
MOTO S/D 5AV844614 LAPXCHLA580036532  
MOTO 013IDA 1P52FMH\*61636856\* BORRADO  
MOTO S/D Z5150FMH\*85A00128\* \*9PAABBBK56A000291\*  
MOTO S/D JD17E-W101668 9C2JD170WR101668  
MOTO S/D 1E50FMG-302416- \*LC6PAGA1920024050\*  
MOTO 727GLP LC1P50FMH08046863 8\*8A2XCHL269A001719\*  
MOTO 306JRT JL1P52FMH\*1205201933\* 8CVXCH8A5DA032513  
MOTO S/D LC152FMHD367525 LLCXCHLL981070041  
MOTO S/D KB203905194 \*LC2B8001073900907\*  
MOTO S/D 1P52FMH\*08012221\* \*LRYXCHLA486010729\*  
MOTO S/D C001951 8ELM36110CB001951  
MOTO S/D 1P47FMD61083834 8A6MSS0AA65054203  
M. MODIFICADA S/D MODIFICADO \*LAYPCGB06XJ60000  
MOTO 963IAR JL1P50FMH\*05A165529\* LYLXCGL5151015315  
MOTO S/D 147FMD05050232 \*ILYXCHLA066900559\*  
MOTO S/D 1P52FMH\*71008945\* ILEGIBLE  
MOTO S/D KNI52FMH12010847 ILEGIBLE  
MOTO S/D LF1P50FMH81057536 LYLXCCL5661010158  
MOTO S/D 1P52FMH81450839 NO SE ENCUENTRA  
MOTO S/D 1P52FMH71203381 NO SE ENCUENTRA  
MOTO 503EPK HAO7E67605184 8C1IHAO7007L005028  
MOTO S/D MO00085 8AHJ15050N000753  
MOTO S/D EI033799990BE11A-180985  
MOTO S/D 1P52FMH\*C1007410\* NO SE ENCUENTRA  
MOTO S/D 1P50FMH81035247 F3XCH2G78A006481  
MOTO 805DLY DJ150FMH060430076 HJYCHRA27B800858  
MOTO 642HUZ KC08E1209791 9C2KC08104R097918  
MOTO 513HJY 1P52FMH08061168 \*LBXXCH9J580901168  
MOTO S/D 1P50FMH81192823 \*8A2XCHLV78A001495\*  
MOTO 477JMR 1P52FMID7613919 8OYC1124BDV007890  
MOTO S/D 1P52FMH60965467 \*LP7XCHL0660102575\*  
MOTO 690JLA J1P52FMHD0043261 8CXSMASHSDGS02745  
MOTO S/D KN152FMH\*11081314\* \*9E71CDA73B0027989\*  
MOTO S/D MD34E3107035 9C2MD8400 3R107035  
MOTO S/D SDH150FMG-2-75019780 \*LTMPCGB2275018661\*  
MOTO S/D LF1P52FMH81251080 8CXSMASHSGGS22378  
MOTO S/D JC162FMJ21QMA6F0 \*8BJPCHLJ001000328\*  
MOTO S/D LF1P52FMH\*B1030389\* LYLXCGL58B1161495  
MOTO S/D 1P52FMH\*76508860 \*LX8XCH8087F002075\*  
MOTO S/D 1P52FMH\*B3603661\* \*LRPXCHLC4C3603698\*  
MOTO 464CFB HAO7E13036248 9C2HA07103R036248  
MOTO S/D HAO7EG7601160 \*8A2XCUL249A002348\*  
MOTO S/D 1P50FMH06123337 ILEGIBLE

MOTO 984JJE 162FMHJ\*D2637812\* 80YC51498DV017632  
MOTO S/D LC152FMH2B7001147 LCLXBHLG289101251  
MOTO S/D M152FMI\*0805001071\* \*8020TU0D091000299\*  
MOTO S/D JC3OE77071877 ADULTERADO  
MOTO 066GFB LF1P50FMHA1045181 8EGSMASHFADR104254  
MOTO 021IDA 156FMI11B41808 LHJYCJLA3B2799767  
MOTO S/D \*637531 RH9VR150HYT003160  
MOTO 282HCI 152FMH\*A0452597\* \*8BPC4DLB3AC007246\*  
MOTO S/D 162FMJ11B43593 LHJYCKLA7C2808591  
MOTO S/D ZS162FMJ\*8DA08835\* 8A6RZM15ZFC500784  
MOTO 634IYV 162FMJ\*C2634115\* 8DYC51496DV014037  
MOTO S/D 162FMJ\*C2632232 8DYC51490V012325  
MOTO 960DIS 152FMHCO462636 \*8BPC4DLB7C0475261  
MOTO S/D JL1P52FMH\*1011203164\* 8CVXCH8A8BA009756  
MOTO 638GLT HAO7EG7603212 8CHHA07007L003011  
MOTO 415IGL 1P52FMH61173193 \*LP7XCHL0660102785  
MOTO 545EHV 156FMIA1003488 KMYONF100XC005590  
MOTO S/D OOO1123 80XSMASHFDG00086  
MOTO S/D 162FMJ11814279 LHJYCKLA0B2751939  
MOTO 179GGY LC157FMIHA112142 8A6MAVRXZAC000586  
MOTO 865INL 1P52FMHC1642257 BDYC11073CV028443  
MOTO S/D C007740 NO SE ENCUENTRA  
MOTO 649EOY 1P50FMH\*05093419 LYLXCGL1951026950  
MOTO S/D QJ157FMI9010\* \*8CEEFR012591TR114\*  
MOTO 621EPK 1P52FMH81035231 \*LF3XCH2G48A005241\*  
MOTO S/D KK156FMIB\*08020046\* LKLPCJIN38A020008  
MOTO S/D 1P52FMH\*81035965 \*LF3XCH2G58A005233\*  
MOTO S/D 9014005 8ELM361109B014005  
MOTO S/D 50M110002 8A6MSS0AA3S005785  
MOTO S/D KT1P52FMH\*E0010054\* \*8A2XCHHM9DA080816\*  
MOTO 681IAR KB22\*1011478\* \*8CMKMC110C1C12282\*  
MOTO 744KOF B001112 8ELM12110BB001112  
MOTO 502DAR SDH150FMG2\*65126373\* \*ETMPCGB2365131078\*  
MOTO S/D JC156FMI\*TM81000031\* \*LJCFCJLV281000055\*  
MOTO S/D #77-08658# NO SE ENCUENTRA  
MOTO S/D 162FMJ11837685 LHJYCKLA2B2776129  
MOTO 576GQQ 1P52FMHAJ267818 \*LF3XCGB07AA012428\*  
MOTO S/D 162FMJ\*10B15355 LHJPCJLA2A2638682  
MOTO 102AUY JC41E19064721 20099C2JC41109R064721  
MOTO 534HEV 1P52FMH09051144 8A6MBSVCZAC803347  
MOTO 580III LF1P52FMIB1250695 8CXREV125C0003978  
MOTO 864HZW \*E3J9E\*\*009076\* LL8KE1548CB016888  
MOTO S/D CO48149 8ELM15110CB048149  
MOTO S/D KC08E15140350 9C2KC08105R140350  
MOTO 505EPK 1P54FMI\*08110583 8A6S12B0Z9C902520  
MOTO 791BTM JC30E3287398 9C2JC30103R287398  
MOTO S/D SDH150FM-275098118 \*LTMPCGB2975095561\*  
MOTO S/D 162FMJA1243785 8CVPCKD07A005237  
MOTO S/D NO SE IDENTIFICA \*LTMPCGB2955159613\*  
MOTO S/D BORRADO A GOLPE \*LB7PCMLE082206175\*  
MOTO S/D 8032525 NO SE LOCALIZA  
MOTO 752GAU 6026862 8ELM071506B026862  
MOTO 520HHZ LF1P52FMH\*B1039332\* LYLXCGL52B1161458  
MOTO 390CFD KYSF20\*1900841\* RFBSF20AFI9000791



MOTO S/D 163FM63101066 \*LBXYCMEA38X010144\*  
MOTO S/D NO SE IDENTIFICA LHJYCKLA5A2655834  
MOTO S/D KB20\*3916385\* \*8CMKY0110C1A10124\*  
MOTO S/D 162FMJ\*09003427\* LHJYCKLA502582374  
MOTO S/D KN162FMJ\*11010117\* \*LRYPCKL0XB0013326\*  
MOTO 571DAR/371DAR LF1P50FMH\*81051594\* \*LC6XCHX2760802075\*  
MOTO 949DLY SDH150FMG-75824106 ADULTERADO  
MOTO 471ING 1P52FMHZC017024 8A6MDSPOZCC500163  
MOTO 272CFD GD156FMI186000879 \*LAZTGJLN51080765\*  
MOTO 255ELY 15CO8E2B501435 9C2KCO820BR501435  
MOTO 962KDC 1P52FMH\*C1015444\* 8AHJ2211OCRO14523  
MOTO S/D JS150FMH\*06C01788\* LAPXGHLE660009484  
MOTO S/D E3E7E006382868C6KE132600006452  
MOTO S/D 1P52FMH07300873 LSRXCHLD57130188\*  
MOTO 772HWW KB22\*1009756\* \*8CMKMC110C1C11584\*  
MOTO S/D 1P52FMH10A13527 LHJXCHLOA2A2647353  
MOTO S/D 1P52FMH13090121 8AHJ401100R002390  
MOTO 922EDK LE1P50FMH1229529 8CXSMASHFBCRO5982  
MOTO S/D JL1P52FMH\*1304202642\* 8CVXCH8A9DA036077  
MOTO 878DNN D9152FMJ5148584 \*8BPC4DLB9DC065611\*  
MOTO 111JFB 1P52FMH120772 \*8CEBF4117CX003272\*  
MOTO S/D 150FM-3\*2007006423 NO UBICABLE  
MOTO 637FAD 1P52FMI91003890 ADULTERADO  
MOTO S/D 152FMH\*06051444\* \*LHJXCHLA860493301\*  
MOTO 213HIZ 1P52FMH0B001648 GOLPEADO 8CXFMAFH5BCF13019  
MOTO S/D 9J157FM29010146 \*8CWFR012591CR1092\*  
MOTO S/D SK156FMI\*0600017200\* 9PDABBBH871135970  
MOTO 862DAC JL1P50FMH\*06A170006 LYLXCCL5061028343  
MOTO S/D 16B203915788 \*8C11KY0110B1A1001  
MOTO 178GWI 1P52FMH0A051747 8CXSMASHSBGS05239  
MOTO S/D J1P52FMH1002200430 8CVXCH2G9AA007817  
MOTO 065DFH 1P52FMH\*71067637\* \*LF3XCGB037B002837\*  
MOTO S/D 525GYR 162FMJA2614673 \*LRPNCKLGXA2610875\*  
MOTO 750DAR 1P50FMH\*06160497\* ILEGIBLE  
MOTO S/D F128124981 ADULTERADO  
MOTO S/D 5014842 8LM162005B014842  
MOTO S/D RPM003303 \*LY4YXBH08A1001842\*  
MOTO 833DXR 1P52FMHB1086673 LFSXCH2G58A013266  
MOTO S/D 16B221015304 \*8CMKMC110\*\*C1C14632\*  
MOTO 476ING KE25J201393\*8CMPU0125C16  
MOTO S/D 1P50FMH\*06003379\* LAAAXKHG061000544  
MOTO 404DKC 1P52FMH\*08304570 \*LSRXCHLD581305515\*  
MOTO S/D SDH150FMG\*65133175\* \*LTMP5GB2365137463\*  
MOTO 100GFB SDH157FMI-C\*93041256\* \*LALPCJF85A3001060\*  
MOTO 476CBL 152FMH0612444 LIMADO  
MOTO S/D KK156FMI-B\*09020128\* \*8CMGKO125A1GK1029\*  
MOTO S/D LC163FML\*08118063\* 8EGSMX2008G000062  
MOTO SD 1P52FMH05AD2343 LJ4XCHLJ861004455  
MOTO 778IAR LS1P52FMI88813686 8CVJCKL06BA006582  
MOTO 915IMQ 1P52FMH\*CA123237 8AHJ36118CR006119  
MOTO S/D KN152FMI\*08070126\* LRYPCPLY380019521  
MOTO S/D JL1P50FMH05A213054 LYLXCGL5151020576  
MOTO 466ILY 162FMJ\*B2619123\* \*LRPNCKLG2B2614534\*  
MOTO S/D 15010342 LAWFPF30XBB756143

MOTO 758GEB QJ157FMI8615871 LBBPEJJ018B36360  
MOTO S/D 1P52FMHBA057713 \*LXYXCHL04B0510031\*  
MOTO S/D E3D5E038418BC6KC1279A0023738  
MOTO 794IAR 152FMH\*09003132\* LHJXCHLA092558697  
MOTO 892LCH YG1P52FMH\*C9061068\* 8C5YBGGC630004479  
MOTO 945DYZ JC30E407727 9C2JC30104R077271  
MOTO S/D SK150FMI0500014277 9PDABBBI451113189  
MOTO S/D 162FMJ71130212 \*LF3YCK3A67D001605  
MOTO 896IXB C0OS3390 8ELM05150CB053390  
MOTO 655CAO 163FML\*10129484 \*9PEARGE54AF000650\*  
MOTO S/D 1018037 ADULTERADO  
MOTO S/D QJ153FMH-2\*85010228\* LAWXEH0E08B345464  
MOTO S/D 15B203909787 \*LC2B8001083900508\*  
MOTO S/D 1P52FMH81116868 \*8BMBSU00081010951\*  
MOTO S/D LF1P50FMH91308058 8FGSMASHFAGRO  
MOTO 785KOF EQQ1127 8ELM15110EB001127  
MOTO S/D M153FMH2062000245 8A8MBSCAC6C200508  
MOTO S/D 9013991 ELM3G11098013991  
MOTO 559HBT 161FMJ\*A1001594\* \*LF3PCKD09AD000246\*  
MOTO S/D JC30C6637705 \*LTMJD19A1C5312933\*  
MOTO 578DLY LF1P50FMH\*81021486\* LSRXCHLD18A10103352  
MOTO 756DLY KB203910211LC2B8001083900745\*  
MOTO 700JCV 1P52FMH\*ZC053601\* NO SE ENCUENTRA  
MOTO JVV488 SDH157FMI-C-63022462 \*LALPCJF8563257531\*  
MOTO 868JFK 1P52FMH70380776 RAYADO  
MOTO 317CFD ILEGIBLE \*LTMPCGB2755180542\*  
MOTO S/D 167FML11B08938 LHJYCLLB2B2791017  
MOTO 618AEL 162FMJ\*8B403409 \*8BMBKT00061002756\*  
MOTO S/D LF1P50FMH71331499 LSRXCHLK17A625198  
MOTO S/D 1P52FMHOB806980 LYLXCGL5471064138  
MOTO S/D 1P52FMHOB603676 \*8A2XCHLN4BA016947\*  
MOTO S/D AD1P52FMIF0046344 NO SE ENCUENTRA  
MOTO 374EVZ/S/D 1P52FMH1215082 \*LYLXCGLMHI008182\*  
MOTO S/D BORRADO A GOLPE 8A6MRXGHZEC501683  
MOTO 585HFX 1P52FMHBA10382 8AHJ36110BR000015  
MOTO 504HPQ 1P52FMHB1175879 \*LFJXCH2G9BA001063\*  
MOTO 568DAR 152FMH\*61253119 8BMBSU00061200775  
MOTO S/D 8A509810 \*LX8PCMP03AF000719\*  
MOTO 896EPK YG1P52FM\*AJ000793\* \*LY4YXBHG8AJ000793\*  
MOTO S/D DK50XE1152151 0K50XF1504753  
MOTO 587DAR 150FM-3\*2006006988\* ILEGIBLE  
MOTO S/D 1P52FMH81036045 F3XCH2G48A005191\*  
MOTO 413GGC KN182FMJ92\*A1090078\* \*LRYPCCKLO8A0013565\*  
MOTO S/D 147FM-4-2006001988 ILEGIBLE  
MOTO 813ERY 161FMJ\*91007077\* \*LF3PCKD089D002940\*  
MOTO S/D 7060867 8FLM162007B000861  
MOTO S/D JA0AEIC700570 9C2JA04106R700570  
MOTO S/D JC158FMI211A293979 \*LAAAJKJV2B0004783\*  
MOTO 983GPX LC157FMIIAO51216 8A6MAVRX7BC000155  
MOTO S/D JCSoE41021940 9C2JC80401R011940  
MOTO S/D ZS167FML-3\*8B800415\* 8CVJCML0XBA002322  
MOTO 538EPK 152FMH81035463 LF3XCH2G98A006479#  
MOTO S/D LF1P50FMHA1343642 8CXSMASHFBGRO7365  
MOTO S/D JL1P52FMH1209202797 CH2G3CA046535

MOTO S/D JC30E23634847 9C2JC30213R634884  
MOTO 812IAR (TRUCHO) A038092 8ELM15110AB038092  
MOTO S/D 1P52FMH13071323 8AHJ36110ER009624  
MOTO S/D YG1P52FMHBJ002173 8AHJ26110BR000159  
MOTO S/D F128-117514 LIMADO  
MOTO 453GIK 1P52FMHZ0041790 8AGMBSVCZEC800479  
MOTO 894IIT JL1P52FMH11122002131 8CVXCH8ACA020021  
MOTO 857EBQ SDH150FMG-275095979 LTMPCGB257509349  
MOTO 945DXR LF1P50FMH81006791 LYLXCGLO881005955  
MOTO S/D CVDA00A000995 8CVXCH261DA057499  
MOTO 943EAW JC30E-2F1002208 9C2JC30201R002208  
MOTO 791IZP SDH150FMG-2C5839493 8CHPCEB21DL012475  
MOTO 125DLB 161FMJ#71075177# #LF3PCKD057D006330#  
MOTO 536HEV 162FMJC1565231 6A6MA1XR2DC500818  
MOTO S/D KB2210173828CMKMC11#0D1C10140  
MOTO 821DXR SDH150FMG-275116875 LTMPCCB2475114462  
MOTO S/D 1P50FMH0B411991 8CXSMASHFCGC16236  
MOTO 220HNJ JL158FMI-7#11A151892 LAAAJKJV5B00000002  
MOTO S/D ME08E-3100449 JH2ME0805VM106447  
MOTO 971IIT JC41E19004471 20099C2JC41109R004471  
MOTO 179GBU JC1P52FMIRJ91038724 8BJXCHL1091001126#  
MOTO 899GNB HA07E-X100302 9C2HA070XWR100302  
MOTO 559ISN KB2512027878CMKY0125C1B10048#  
MOTO S/D MC35E-8029607 9C2MC35008R029807  
MOTO 780HWW 161FMJ31324410# LF3PCKD03BP011163  
MOTO S/D 1P52FMH80401838# #LEAXCH5028B90250#  
MOTO S/D KC08E26156274 8CHKC21106L008728  
MOTO S/D 1P52FMHA1291951 LF3XGB00AA015302  
MOTO 984JBB 161FMJC1566483# 8A6MRXGH2DC800986  
MOTO 160HIV 152FMH#B0600418# #8020KUO10C1001591  
MOTO S/D 1P52FMIE7617433 8DYC11249EV010019  
MOTO 467IKB KCO8ELB600972 9C2KC0820BR500972  
MOTO S/D LC152FMHZ87000271 LCLXBHLG489100375  
MOTO S/D 162FMJ09002827 LHJPCKLA292554521  
MOTO S/D 1P52FMHC6609033 8DYCX1077DV003907  
MOTO S/D KB22#1017491# #8CMKMC110# #81C10242#  
MOTO 696GLL 162FMJ#A5011244# 8AHJ30150AR000243  
MOTO S/D KB22#1009941# #8CMKMC110# #C1C12542#  
MOTO S/D 162FMJ13A02826# LHJPCKLA1D2893621  
MOTO S/D 167FML#11D06985#LHJYCLLB2B2761709  
MOTO 599LBH CVFA10A001266 8CVXCH26G6FA086841  
MOTO 157DKC JC30E24019121 9C2JC30204R019121  
MOTO S/D 152FMH#VA130272# LLCX4NCJ580100491  
MOTO S/D 1P51FMH#13071555# 8AHJ40110ER003925  
MOTO 428CAT KCO8E14038814 9C2KC08104R036814  
MOTO S/D 161FMJB1022533# 8AHJ23150BR000965  
MOTO S/D 162FMJ#C6003498# #LRPNCKLK4D600320012  
MOTO S/D E316E-002145 9C6KE069050001503  
MOTO 670LHC QJ157FMI#660077838 1WPFJ0C86728226  
MOTO 187CBL 4002856 LIMADO  
MOTO S/D 1P52FMH#51365159 #8BMBSU00061003478  
MOTO S/D 1P52FMH#AA082021# #LXYXCHL08A0259898  
MOTO 379DKC JC152FMH#RD81001100# LJCXCHLG581000565#  
MOTO 023JJU KB22#1018022# #8CMKMC110# #D1C10391#

MOTO 670ILK 157FMI#0A106845# LAAACJLR0B1120238  
MOTO 359GQV 1P52FMI#A7504497# #LCRXCJCE1A7504354#  
MOTO 836DXR LF1P50FMH#81403826# LYLXCGL5881092610  
MOTO S/D 1P50FMH#06123709 LWGXCHL4462008974#  
MOTO S/D 70M701717 8A6MSS0AA25073539  
MOTO 586GQQ 161FMJ#A1291848# #LF3PCKD0XAD008517#  
MOTO 433IGL KB22#1012831# #8CMKMC110# #C1C14206#  
MOTO S/D 9017710 8ELM32125B017710  
MOTO 715IYU KF163FMH#B2054762 8EG5MX20CBEM00647  
MOTO 986DXR 152FMH#08426742 LB7PCHLE882208188  
MOTO 642HGI #1P52FMH#OA103604# #8A2XCHLM6BA039797#  
MOTO S/D KB22#1006722# #8CNKHC110#C1C11347#  
MOTO 451CFD 1P50FMH#0611847 LYLXCCL5261020170  
MOTO 423IQT KN152FMH#110093157# #LRYPCHLZXB0075853  
MOTO 053LKT KCO8EZ8105348 9C2KCO8208R105348  
MOTO 545EPK 1P52FMH#07301813 #L5RXCHLD771302758#  
MOTO 468DKC LC152FMH285000458 LCLXDHLEX891  
MOTO 221CPR 161FMJ#62003003# 8BMBKT00061001554  
MOTO 908IXB JC1P52FMHRJA1024794 \*8BJXCHI1191003448\*  
MOTO 310GHF KCC8E17097576 1C2KC08107R097576  
MOTO 095IDA \*B1225257\* LF3XCH2G88A003192\*  
MOTO 664CXR SDH150FMG-2\*65021832\* LTMPCGB2465031140  
MOTO 872KKX JC30E2G103977 9C2JC30203R103977  
MOTO 547JVX ZS167FML-3\*8E800\* 8CUJCNL0BDA  
MOTO 492DTB 1P52FMH\*81035971\*  
MOTO 533LDW 161FMJ\*13Y16642\* 8DGC51500EG000440  
MOTO 927JFK 1P52FMH\*D1024123\* \*LF3XCH2G1DA001237\*  
MOTO S/D 161FMJ\*81008992\*  
MOTO S/D C90E-2021948 LAAAXKHGX61103727  
MOTO 018IQH 1P52FMH\*ZC025222\* 8A6MBSVVCZCC54175  
MOTO 956CSL 161FMJ\*51441266\* \*LF3P0KDO75D003121\*  
MOTO S/D JC152FMH\*RD81000822\*  
MOTO 614HUZ 156FMI\*91016668\* \*50340\*  
MOTO 876KFX KT1P52FMI\*D0063153\*  
MOTO 713CXR QJ153FMH-2\*67155131\*  
MOTO S/D LF1P50FMH\*81094553\* LYLXCGL1381006035  
MOTO S/D 5020219 8ELM071505B020219  
MOTO S/D GDI156FMI\*1600124\* JH2ME0505RK801124  
MOTO S/D QJ153FMH-2\*67162302\*  
MOTO 575JOG DY162FMJ-2D5068255\* \*8BPZ4KLYXDC008983\*  
MOTO S/D 1E50FMG-T0121519- \*LC6PA6A1380805557\*  
MOTO 641IYU C036442  
MOTO S/D 162FMJ\*A1105951\* \*LF3YCK3A0AD000747\*  
MOTO 696IYV 1P50FMH-A\*12A157259\*  
MOTO 155HIZ QJ153FMH-2\*85024122\*  
MOTO 241DKC  
MOTO S/D YG1P52FMH\*B1006463\*  
MOTO S/D 704220  
MOTO S/D JC156FMI\*TM81005014\* \*LJCFCJLV081000913\*  
MOTO 172GNW 162FMJ\*10B26907\* LHJPCKLA6A2665027  
MOTO 821IAR 1P52FMH\*B3603944\* \*LRPXCHLC4C3604088\*  
MOTO 497IKV 1P52FMH\*C3604188\*  
MOTO 874HDU LF1P50FMI\*B10321915\*  
MOTO 891HMJ LF163FML\*B2058134\* 8EGSMX200BG003346

MOTO S/D 162FMJ\*12B15774\* LHJYCKLA7C2823933  
MOTO S/D C100KSE-502395 9C2HA05015RS01605  
MOTO 684JCV C037042  
MOTO 922KHX KN152FMI\*B0400746\*  
MOTO S/D KB251202016\* \*LC2B8102081200198\*  
MOTO 152HSS YG1P52FMH\*BJ002867\* 8AHJ26110BR001013  
MOTO 519DLY HA07E65000871 9C2HA07605R000871  
MOTO 746KAB KT1P52FMH\*D0027925\*  
MOTO S/D 1P47FMD51117683 LF3YCD365D000049  
MOTO 629IVU 1P52FMH\*C1508289\*  
MOTO 331HHP JC152FMH\*RD81001961\* \*LJCXCHL6X81000867\*  
MOTO S/D 162FMJ\*12830377\* LHJYCKLA9C28508  
MOTO 622JCV 1P52FMH\*C1146763\*  
MOTO 892JBB KB22\*10119948\*  
MOTO S/D 161FMJ\*C1049328\* \*LF3PCKD05CA016903\*  
MOTO S/D 150FM-3\*2006001329\*  
MOTO 584DAR SDH157FMI-C\*63028861\* \*LALPCJF8563264477\*  
MOTO 803IMI KN152FMH\*11100095\*  
MOTO S/D 162FMJ\*10B17654\* 8EGSM\*200A6002031\*  
MOTO S/D LC152FMHFD151324 LLCXEHL57107844  
MOTO 220CYP 161FMJ\*06030869\* LAAECKLA161154969  
MOTO 954DLY YG1P52FMH\*89002590\*  
MOTO S/D \*630072\* H9HF125LXT043351  
MOTO 857DAR 161FMJ61172998 LF3PCKD006D003608\*  
MOTO 715EQY 8011904 8ELM301258B041904  
MOTO S/D LF1P50FMH\*81012873\*  
MOTO 764EPK JL1P47FMF-5\*09A316171\*  
MOTO 815HMJ LF162FMJ\*810088871\* \*LF39CKDO481014249\*  
MOTO 659KAB KB22\*1019258\* \*8CNKC110\*\*E1C10418\*  
MOTO 873IAR LF1P52FMI\*B1287117\*  
MOTO 245HIZ 1P52FMH\*08013758\* \*8A2XCHLL3BA034984\*  
MOTO S/D KB20\*3915416\*  
MOTO 999BGN  
MOTO S/D SDH150FMG-2\*75809118\* 8CHPCGB208L002203  
MOTO 566DXR SDH150FMJ-2\*55117985\* \*LTMPCGB2355118040\*  
MOTO S-D SDH150FMG-2\*65033071  
MOTO 605EPK SDH150FMG-2\*85078524\*  
MOTO 622GXN MC3SE-6016083 9C2MC35006ROI6083  
MOTO S-D 162FMI\*12829597\* LHYCKLA2C2846715  
MOTO 012JFL 161FMJ\*C1426833\* \*8BMBKT000D1006365\*  
MOTO 179HYJ 1P52FMH\*70003733\*  
MOTO 582HUZ KB22\*1007853\* \*8CMKMC110\*\*C1C11469\*  
MOTO A000FBD 1P52FMH\*F1511873\* 8CVXCH265FA100650  
MOTO 948IIT B041103  
MOTO 059HBC JL1P50FMH\*06A087376\* LYLXCGL5061024153  
MOTO S-D KT1P52FMI\*D0008597\* 8CXREV125D0000208  
MOTO S-D 1P52FMH\*71164559\*  
MOTO 507HEV 162FMJ\*08203045\* \*LSRPCKLG08210342\*  
MOTO 161GKG  
MOTO S-D QJ153FMI-2\*67195345\*  
MOTO 749EDT JC30E12179915  
MOTO 867HMJ 1P47FMF\*0AC00222\* 8AGH944AHBC904360  
MOTO 936JZM E3HGE-022620 8CGKE1273D0095992  
MOTO 815JCV 0.53464 8ELMO5150CBO53464

MOTO 904KDC LC162FMJ\*J00592034\* 8A6PCKD07CE000825  
MOTO S-D JL1P52FMH\*1304202305\*  
MOTO 027HRK B029202  
MOTO 098JRU 161FMJ\*D1074417\* 8AGMRXGHZEC500024  
MOTO S-D 1P52FMI\*08100944\* LD7XTJLK5825000944  
MOTO S-D KB20\*3917015\*  
MOTO 923CKE QJ153FMH-2\*67001596\*  
MOTO 656DXR 1P50FMH\*6111966\* LAAXKHAB061002935  
MOTO 606DAP JC30E12208545 9C2JC301028208545  
MOTO 503FAD 152FMJ\*A2705514\* LSRPCKLE2A2705894  
MOTO 441IVQ 1P52FMH\*CAO94223  
MOTO 139GVA MI52FMI\*0805000975\* \*8D20TU02091000364\*  
MOTO S-D C068376 8ELM116200CB068376\*  
MOTO S-D JL253-3\*10A002352\* \*LAAAEKNB6A0000223\*  
MOTO 603IWH B072585 SELMO5150BB072585  
MOTO S-D 1E50FM\*980303588\* \*LAEKEZ100\*NG000378\*  
MOTO 942CHQ 01B18E2251201C20F15065  
MOTO 882KDC 167FML\*D6605178\* \*LRTNCMLJ2D6605156\*  
MOTO S-D KN162FMJ92\*B1055059\* LRYPCKL00B0015747\*  
MOTO 129HRU 162FMJ\*11B15272\* LHJYCKLA4B2754763  
MOTO S-D 1P52FMH\*4323396\* 8BMB5000\*\*41001338\*  
MOTO S-D SK156FMI\*060019200\* 9PDABBB5171136616  
MOTO S-D 163FMI-2M\*82046974\* \*LF3YCM22038D003673\*  
MOTO S-D 1272E3087 37Q00319 AB0085  
MOTO S-D B027927 8ELMO5150BB027927  
MOTO S-D 156FMI\*11B05487\* LHJYCJLA7B2749020  
MOTO 283GWI E3LSE-243774 ESKE1978D0009030  
MOTO 552EHV 163FML\*61197284\* \*LEAPCK20580001131\*  
MOTO 617KNS KN162FMJ\*EA117408\* 8E72A5B17F0000014\*  
MOTO 109ITF LF1P52FMH\*71465636\* LSRXCHLLC47A628833  
MOTO 178GVA 1P52FM\*A760534\*  
MOTO S-D 152FMH\*7070081\* ST70-6405885  
MOTO S-D A017959 8ELM32125AB017959  
MOTO S-D 150FM-3\*2008023546\*  
MOTO 443LLC E302E-032574  
MOTO S-D B010277  
MOTO S-D HA0714025775  
MOTO 092HRU 1P52FMH\*0AB01502\*  
MOTO 139CPD CD\*92950\* \*92950\* TIENE TRAILER  
MOTO S-D IAA007  
MOTO S-D 1P52FMH\*BA140759\*